

D-Link Multifunction Print Sever Compatibility List

● Document Revision History

| Version | Date | Description | Edited By |
|---------|----------|---------------|-----------|
| 1.0 | 2009/7/1 | First Release | Richard |

Multifunction Printer Compatibility List

Device: DPR-1040 FW/1.00; SW/A08

Report marked as "NA": Printer doesn't support this function

Report marked as **Fail**: The function is fail. PTR No will be added in 'Note'

Report marked as **Fail**: 1. LPR/RAW is also fail with HP EN3700 print server.

2. The functions is also fail even connect printer to host PC directory.

| Company | Model name | Power cycle/USB cycle test | LPR printing | Raw data printing | Auto printing | Manual Printing | Fax via Printer driver | Fax via Utility | Scan via Utility | Scan via Windows Utility | Copy function | Storage access via Windows UI | Storage access via Utility | Control Panel | ink & port status | Note |
|---------|------------|----------------------------|--------------|-------------------|---------------|-----------------|------------------------|-----------------|------------------|--------------------------|---------------|-------------------------------|----------------------------|---------------|-------------------|------|
| Brother | Brother | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | |

| | | | | | | | | | | | | | | | | |
|---------|----------------------------|----|------|------|------|----|----|----|----|----|----|----|----|----|----|---|
| | MFC 210c | | | | | | | | | | | | | | | |
| Brother | Brother MFC 3240c | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | |
| Brother | Brother MFC 640CW | OK | OK | OK | OK | OK | OK | NA | OK | OK | OK | OK | OK | OK | OK | |
| Brother | Brother MFC-58 40CN | OK | OK | OK | OK | OK | OK | NA | OK | OK | OK | OK | OK | OK | OK | |
| Brother | Brother MFC-88 0CDN | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | |
| Canon | Canon MultiPa ss F30 | OK | Fail | Fail | Fail | OK | NA | NA | OK | NA | NA | NA | NA | OK | OK | Driver Not support LPR/RAW printing |
| Canon | Canon 865R | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | OK | OK | |
| Canon | Canon 960i | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | OK | OK | |
| Canon | Canon LBP320 0 | OK | CAPT | CAPT | Fail | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | Driver Not support LPR/RAW printing |
| Canon | Canon | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | OK | OK | |

| | | | | | | | | | | | | | | | | |
|-------|-------------------------|----|----|----|----|----|----|----|----|----|----|----|----|------|----|----------------------------|
| | MP130 (MFP) | | | | | | | | | | | | | | | |
| Canon | Canon MP370 (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | NA | OK | OK | NA | OK | |
| Canon | Canon MP450 (MFP) | ok | OK | OK | OK | OK | NA | NA | ok | ok | OK | OK | OK | OK | OK | |
| Canon | Canon MP500 (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | NA | OK | OK | |
| Canon | Canon MP600 (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | NA | OK | |
| Canon | Canon MP760 (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | NA | OK | |
| Canon | Canon MP780 (MFP) | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | NA | NA | NA | OK | |
| Canon | Canon MP830 (MFP) | OK | OK | OK | OK | OK | OK | NA | OK | OK | NA | OK | NA | OK | OK | |
| Canon | Canon MP950 | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | Fail | OK | * MANTIS BUG NO:0001039 |

| | (MFP) | | | | | | | | | | | | | | | |
|-------|-----------------------------|----|------|------|----|----|----|----|----|----|----|----|----|----|----|--|
| Canon | Canon S400 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | |
| Canon | Canon BJ F890-P D | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | |
| Dell | Dell A920 | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | NA | NA | NA | OK | Change to winprint for LPR/RAW printing |
| Dell | Dell A940 | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | NA | NA | NA | OK | Change to winprint for LPR/RAW printing |
| Dell | Dell AIO 962 | OK | Fail | Fail | OK | OK | NA | NA | OK | OK | OK | OK | OK | OK | OK | 1. Scan issue: The maximum scan resolution of Dell AIO 962 is 600 dpi. 2. Driver Not support LPR/RAW printing |
| Dell | Dell Mono Laserjet MFP 1125 | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | NA | NA | OK | OK | |

| | | | | | | | | | | | | | | | | |
|-------|--------------------------------|----|------|------|----|------|----|----|----|----|----|----|----|----|----|--|
| Dell | Dell Photo 966 | OK | Fail | Fail | OK | OK | NA | NA | OK | OK | OK | OK | OK | NA | OK | Driver Not support LPR/RAW printing |
| EPSON | EPSON 480SX U | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | |
| EPSON | EPSON C60 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | |
| EPSON | EPSON C63 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | |
| EPSON | EPSON AcuLas er C1100 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | OK | OK | |
| EPSON | EPSON CX150 O (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | NA | NA | NA | OK | |
| EPSON | EPSON CX381 O (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | NA | NA | NA | NA | OK | |
| EPSON | EPSON CX410 O (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | NA | NA | NA | OK | |
| EPSON | EPSON CX470 | OK | OK | OK | OK | Pass | NA | NA | OK | OK | OK | OK | OK | OK | OK | |

| | | | | | | | | | | | | | | | | |
|-------|----------------------------------|----|----------------------------------|----------------------------------|----|----|----|----|----|----|----|----|----|----|----|---------------------------------|
| | 0 (MFP) | | | | | | | | | | | | | | | |
| EPSON | EPSON CX480 0 (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | NA | OK | |
| EPSON | EPSON CX510 0 (MFP) | OK | Bidirectional Printer | Bidirectional Printer | OK | OK | NA | NA | OK | OK | OK | NA | NA | OK | OK | Not support LPR/RAW printing |
| EPSON | EPSON CX780 0 (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | OK | OK | |
| EPSON | EPSON Stylus CX947 5fax | OK | OK | OK | OK | OK | NA | NA | OK | OK | NA | OK | OK | NA | OK | |
| EPSON | EPSON Stylus CX830 0 | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | NA | OK | |
| EPSON | EPSON EPL-62 00L | OK | Bidirectional Printer | Bidirectional Printer | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | Not support LPR/RAW printing |
| EPSON | EPSON LP-130 0 | OK | Bidirectional Printer | Bidirectional Printer | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | Not support LPR/RAW printing |

| | | | | | | | | | | | | | | | | |
|-------|---------------------------------|----|----|----|----|----|----|----|----|----|----|----|----|----|----|--|
| EPSON | EPSON PM-800 DC | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | |
| EPSON | EPSON PM-T99 0 | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | OK | OK | |
| EPSON | EPSON RX-630 | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | OK | OK | |
| EPSON | EPSON Style Photo R310 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | NA | OK | |
| EPSON | EPSON Style Photo R800 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | |
| EPSON | EPSON Style Photo 890 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | |
| HP | HP 960C | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | NA | |
| HP | HP Color LaserJ | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | NA | |

| | | | | | | | | | | | | | | | | |
|----|--|----|----|----|----|----|----|----|------|------|----|----|----|------|----|---|
| | et 1500L | | | | | | | | | | | | | | | |
| HP | HP Color LaserJet 1600 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | NA | |
| HP | HP Color LaserJet 2600n | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | NA | |
| HP | HP Color LaserJet 2605 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | NA | |
| HP | HP Color LaserJet CM 1015 MFP | OK | OK | OK | OK | OK | NA | NA | Fail | Fail | NA | NA | NA | Fail | OK | <p>1. Scanning is very slow.(The same as local.)</p> <p>2. Scanning breaks down and appears error message.(The same as local.)</p> <p>3. Control panel function does not work.(The same</p> |

| | | | | | | | | | | | | | | | | |
|----|-----------------|----|------|------|----|----|----|----|----|----|----|----|----|----|----|---|
| | | | | | | | | | | | | | | | | as local.) |
| HP | HP Deskjet 3745 | OK | Fail | Fail | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | NA | LPR & Raw data printing fail, that's Vista driver issue, MFP/Printer standard TCP/IP LPR or Raw data printing are work in Windows XP. (EN3700 is fail too in Windows Vista) |
| HP | HP Deskjet 3845 | OK | Fail | Fail | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | NA | LPR & Raw data printing fail, that's Vista driver issue, MFP/Printer standard TCP/IP LPR or Raw data printing are work in Windows XP. (EN3700 is fail too in Windows |

| | | | | | | | | | | | | | | | | | |
|----|-----------------|----|------|------|----|----|----|----|----|----|----|----|----|----|----|--------|--|
| | | | | | | | | | | | | | | | | Vista) | |
| HP | HP Deskjet 3930 | OK | Fail | Fail | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | NA | NA | LPR & Raw data printinig all is fail.(EN3700 is fail too.) |
| HP | HP Dsekjet 3940 | OK | Fail | Fail | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | NA | NA | LPR & Raw data printing fail, that's Vista driver issue, MFP/Printer standard TCP/IP LPR or Raw data printing are work in Windows XP.(EN3700 is fail too in Windows Vista) |
| HP | HP Deskjet 5740 | OK | Fail | Fail | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | OK | LPR & Raw data printing fail, that's Vista driver issue, MFP/Printer standard TCP/IP LPR or Raw data |

| | | | | | | | | | | | | | | | | |
|----|------------------|----|-------------|-------------|----|----|----|----|----|----|----|----|----|-----|-------------|--|
| | | | | | | | | | | | | | | | | printing are work in Windows XP.(EN3700 is fail too in Windows Vista) |
| HP | HP Deskjet 6540 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | |
| HP | HP Deskjet 6840 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | N/A | Fail | When printer is cover open or paper out, port monitor does not display port status correctly. (The same as local.) |
| HP | HP Deskjet D1330 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | |
| HP | HP Deskjet D2360 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | |
| HP | HP Deskjet D4160 | OK | Fail | Fail | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | NA | 1. LPR & Raw data printing fail, that's Vista driver issue, MFP/Printer |

| | | | | | | | | | | | | | | | | |
|----|---------------------------------|----|-----|-----|----|----|----|----|----|----|----|----|----|-----|-----|---|
| | | | | | | | | | | | | | | | | standard TCP/IP LPR or Raw data printing are work in Windows XP.(EN3700 is fail too in Windows Vista) |
| HP | HP Deskjet F380 | OK | OK | OK | Ok | OK | NA | NA | NA | OK | OK | NA | NA | NA | NA | |
| HP | HP LaserJet 1012 (GDI) | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | |
| HP | HP LaserJet 1020 (GDI) | OK | GDI | GDI | OK | OK | NA | NA | NA | NA | NA | NA | NA | N/A | N/A | Not support LPR/RAW printing |
| HP | HP LaserJet 1022 (GDI) | OK | GDI | GDI | OK | OK | NA | NA | NA | NA | NA | NA | NA | N/A | N/A | Not support LPR/RAW printing |
| HP | HP LaserJet 1160 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | N/A | N/A | |

| | | | | | | | | | | | | | | | | |
|----|--------------------------------|----|----|----|----|----|----|----|----|------|----|----|----|-----|-----|--|
| HP | HP Laserjet 1300 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | N/A | N/A | |
| HP | HP LaserJet 2200D | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | N/A | N/A | |
| HP | HP LaserJet 3015 | OK | OK | OK | OK | OK | NA | NA | OK | OK | NA | NA | NA | OK | OK | |
| HP | HP LaserJet 3050 | OK | OK | OK | OK | OK | NA | NA | NA | Fail | NA | NA | NA | N/A | NA | Scanning breaks down with high dpi and appears error message. (The same as local.) |
| HP | HP LaserJet M1005 MFP | OK | OK | OK | OK | OK | NA | NA | NA | OK | NA | NA | NA | | OK | |
| HP | HP Laserjet M1522 n | OK | OK | OK | OK | OK | NA | NA | OK | Fail | NA | NA | NA | OK | OK | Scanning will be interrupted, when solution set to 1200 DPI. Mantis bug number: |

| | | | | | | | | | | | | | | | | |
|----|----------------------------------|----|------|------|----|----|----|----|----|----|----|----|----|------|-----|--|
| | | | | | | | | | | | | | | | | 0000938. |
| HP | HP Laserjet P3005 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | |
| HP | HP Officejet 4110 (MFP) | OK | Fail | Fail | OK | OK | NA | NA | NA | OK | NA | NA | NA | NA | NA | LPR & Raw data printing fail, that's Vista driver issue, MFP/Printer standard TCP/IP LPR or Raw data printing are work in Windows XP.(EN3700 is fail too in Windows Vista) |
| HP | HP Officejet 4255 (MFP) | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | NA | NA | Fail | OK | Control panel function does not work.(The same as local.) |
| HP | HP Officejet 5110 (MFP) | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | NA | NA | OK | N/A | |

| | | | | | | | | | | | | | | | | |
|----|----------------------------------|----|------|------|----|----|----|----|----|------|----|----|----|-----|-----|---|
| HP | HP Officejet 5510 (MFP) | | | | | | | | | | | NA | NA | | | |
| HP | HP Officejet 5610 (MFP) | OK | Fail | Fail | OK | OK | OK | OK | OK | Fail | OK | NA | NA | OK | OK | 1. If Scanning DPI is 1200, Scanning will always break down (Local is fail too) 2. LPR & Raw data printing fail, that's Vista driver issue, MFP/Printer standard TCP/IP LPR or Raw data printing are work in Windows XP. (EN3700 is fail too in Windows Vista) |
| HP | HP Officejet 6110 (MFP) | OK | OK | OK | OK | OK | NA | NA | NA | Fail | NA | NA | NA | N/A | N/A | 1. If Scanning DPI is 1200, Scanning will always break down (Local is fail too) |

| | | | | | | | | | | | | | | | | |
|----|----------------------------------|----|----|----|----|----|----|----|----|----|----|----|----|-------------|----|--|
| HP | HP Officejet 6210 (MFP) | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | NA | NA | OK | OK | |
| HP | HP Officejet 6310 (MFP) | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | |
| HP | HP Officejet 7210(MFP) | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | |
| HP | HP Officejet 7310 (MFP) | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | |
| HP | HP Officejet 7410 (MFP) | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | |
| HP | HP Officejet 9130 (MFP) | OK | OK | OK | OK | OK | OK | OK | OK | OK | NA | OK | OK | Fail | NA | 1. Control panel function does not work. (The same as local.) |

| | | | | | | | | | | | | | | | | |
|----|---|----|----|----|----|----|----|----|----|----|----|----|----|-----|-----|--|
| HP | HP Officejet t Pro K850 (MFP) | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | N/A | N/A | |
| HP | HP Photos mart 1215 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | NA | OK | |
| HP | HP Photos mart 2575 (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | OK | OK | |
| HP | HP Photos mart 2610 | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | |
| HP | HP Photos mart 2710 | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | |
| HP | HP Photos mart | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | OK | OK | |

| | | | | | | | | | | | | | | | | |
|----|------------------------------|----|----|----|----|----|----|----|----|----|----|----|----|-----|-----|--|
| | 3210 | | | | | | | | | | | | | | | |
| HP | HP Photos mart 3310 | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | |
| HP | HP Photos mart 335 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | N/A | N/A | |
| HP | HP Photos mart 375 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | OK | OK | |
| HP | HP photos mart 385 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | N/A | N/A | |
| HP | HP photos mart 422 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | N/A | N/A | |
| HP | HP photos mart 425 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | |

| | | | | | | | | | | | | | | | | |
|----|------------------------------|----|----|----|----|----|----|----|----|----|----|----|----|-----|-----|--|
| HP | HP photos mart 428 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | |
| HP | HP Photos mart 475 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | N/A | N/A | |
| HP | HP Photos mart A516 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | NA | OK | |
| HP | HP Photos mart A616 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | NA | OK | |
| HP | HP Photos mart 7150 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | |
| HP | HP Photos mart 7260 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | N/A | OK | |
| HP | HP | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | NA | OK | |

| | | | | | | | | | | | | | | | | |
|----|------------------------------|----|----|----|----|----|----|----|----|----|----|----|----|----|----|--|
| | Photos mart 7550 | | | | | | | | | | | | | | | |
| HP | HP Photos mart 7850 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | NA | NA | |
| HP | HP Photos mart 7960 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | NA | NA | |
| HP | HP Photos mart 8050 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | NA | NA | |
| HP | HP Photos mart 8250 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | NA | NA | |
| HP | HP Photos mart 8450 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | NA | NA | |
| HP | HP Photos | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | NA | OK | |

| | | | | | | | | | | | | | | | | |
|----|--|----|------|------|----|----|----|----|----|----|----|----|----|----|----|--|
| | mart 8750 | | | | | | | | | | | | | | | |
| HP | HP Photos mart C3180 (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | OK | OK | |
| HP | HP Photos mart C4100 (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | OK | OK | |
| HP | HP Photos mart C4385 | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | OK | OK | |
| HP | GP Photos mart C4480 | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | OK | OK | |
| HP | HP Photos mart C5180 (MFP) | OK | Fail | Fail | OK | OK | NA | NA | OK | OK | OK | OK | OK | OK | OK | LPR & Raw data printing fail, that's Vista driver issue, MFP/Printer standard TCP/IP |

| | | | | | | | | | | | | | | | | |
|----|---------------------|----|----|----|----|----|----|----|----|----|----|----|----|-----|----|---|
| | | | | | | | | | | | | | | | | LPR or Raw data printing are work in Windows XP.(EN3700 is fail too in Windows Vista) |
| HP | HP Photosmart C5280 | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | OK | OK | 1. If Scanner DIP is 1200 dpi, Windows Scan wizard is easy to crash (Same as Local) |
| HP | HP Photosmart C6180 | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | |
| HP | HP Photosmart C7280 | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | |
| HP | HP Photosmart D5160 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | NA | OK | |
| HP | HP | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | N/A | OK | |

| | | | | | | | | | | | | | | | | |
|----|-------------------------------|----|----|----|----|----|----|----|----|----|----|----|----|------|----|--|
| | Photos mart D5360 | | | | | | | | | | | | | | | |
| HP | HP Photos mart D7160 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | NA | OK | |
| HP | HP Photos mart D7360 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | NA | OK | |
| HP | HP Photos mart D7460 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | OK | OK | NA | OK | |
| HP | HP PSC 1210 (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | NA | NA | OK | OK | |
| HP | HP PSC 1315 (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | NA | NA | Fail | OK | Control panel function can't work. (It's The same as local .) |
| HP | HP PSC 1350 (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | OK | OK | |

| | | | | | | | | | | | | | | | | |
|----|-------------------------|----|------|------|----|----|----|----|----|----|----|----|----|----|----|---|
| HP | HP PSC 1410 (MFP) | OK | Fail | Fail | OK | OK | NA | NA | OK | OK | OK | NA | NA | OK | OK | 1. LPR & Raw data printing fail, that's Vista driver issue, MFP/Printer standard TCP/IP LPR or Raw data printing are work in Windows XP.(EN3700 is fail too in Windows Vista) |
| HP | HP PSC 1507 (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | NA | NA | OK | OK | |
| HP | HP PSC 1510 (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | NA | NA | OK | OK | |
| HP | HP PSC 1600 (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | OK | OK | |
| HP | HP PSC 1610(MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | OK | OK | |
| HP | HP PSC 2210 | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | OK | OK | |

| | | | | | | | | | | | | | | | | |
|---------|-------------------------------|----|---------------------------------------|---------------------------------------|----|----|----|----|----|----|----|----|----|----|----|---|
| | (MFP) | | | | | | | | | | | | | | | |
| HP | HP PSC 2355 (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | OK | OK | OK | OK | |
| HP | HP PSC 750 (MFP) | OK | OK | OK | OK | OK | NA | NA | NA | OK | NA | NA | NA | NA | NA | Scan fail, when DPI sets to 1200. (The same as local.) |
| Kyocera | Kyocer a FS-102 OD | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | | |
| LEXMARK | LEXMA RK E232 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | NA | |
| LEXMARK | LEXMA RK X1185 (MFP) | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | NA | NA | OK | OK | Change to winprint for LPR/RAW printing |
| LEXMARK | LEXMA RK X1195 (MFP) | OK | Bidirecti onal Printer | Bidirecti onal Printer | OK | OK | NA | NA | OK | OK | OK | NA | NA | OK | OK | Not support LPR/RAW printing |
| LEXMARK | LEXMA RK | OK | Bidirecti onal | Bidirecti onal | OK | OK | NA | NA | OK | OK | OK | NA | NA | NA | OK | Not support LPR/RAW printing |

| | | | | | | | | | | | | | | | | |
|---------|-------------------------------|----|--------------------------|--------------------------|----|----|----|----|----|----|----|----|----|----|----|--|
| | X2350 (MFP) | | Printer | Printer | | | | | | | | | | | | |
| LEXMARK | LEXMA RK X3350 (MFP) | OK | Bidirectional Printer | Bidirectional Printer | OK | OK | NA | NA | OK | OK | OK | NA | NA | NA | OK | Not support LPR/RAW printing |
| LEXMARK | LEXMA RK X4270 (MFP) | OK | Bidirectional Printer | Bidirectional Printer | OK | OK | OK | OK | OK | OK | OK | NA | NA | OK | OK | Not support LPR/RAW printing |
| LEXMARK | LEXMA RK X4550 (MFP) | OK | Bidirectional Printer | Bidirectional Printer | OK | OK | NA | NA | OK | OK | OK | OK | OK | OK | OK | Not support LPR/RAW printing |
| LEXMARK | LEXMA RK X5150 (MFP) | OK | Bidirectional Printer | Bidirectional Printer | OK | OK | NA | NA | OK | OK | OK | NA | NA | OK | OK | Not support LPR/RAW printing |
| LEXMARK | LEXMA RK X7170 (MFP) | OK | Bidirectional Printer | Bidirectional Printer | OK | OK | OK | OK | OK | OK | OK | NA | NA | OK | OK | Not support LPR/RAW printing |
| LEXMARK | LEXMA RK X8350 | OK | Bidirectional Printer | Bidirectional Printer | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | OK | Driver Not support LPR/RAW printing |

| | | | | | | | | | | | | | | | | |
|---------|------------------|----|----|----|----|----|----|----|----|----|----|----|----|----|----|--|
| | (MFP) | | | | | | | | | | | | | | | |
| LEXMARK | LEXMARK Z33 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | 1. When connect printer , it install a new printer (Cpoy1) |
| LEXMARK | LEXMARK Z53 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | OK | 1. When connect printer , it install a new printer (Cpoy1) |
| OKI | OKI-C5400n | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | NA | |
| Samsung | Samsung M-1710 | OK | OK | OK | OK | OK | NA | NA | NA | NA | NA | NA | NA | NA | NA | |
| Samsung | Samsung SCX-4200 | OK | OK | OK | OK | OK | NA | NA | OK | OK | OK | NA | NA | NA | OK | |